

THE SMART MONEY IS ON



Technical Service Bulletin

Double Coin Steer Tire Sidewall Markings

Commercial vehicles, including package cars and light duty trucks are extremely sensitive to steer tire vibration and run out tolerances. Please be advised that the following markings are present on certain Double Coin steer tires to insure optimum performance:

- Steer tire sidewalls with yellow and white dots meet or exceed quality criteria including balance and runout.
 - Optimum for steer positions on all commercial vehicles.
 - Recommended for all other positions on any vehicle with this size as a fitment.
- Products:
 - RR680 (All sizes)
 - FR610 (All sizes)
 - RLB980 (All sizes)
 - RT606+ (All sizes)
 - RT600+ 225/70R19.5/14
 - RT600 245/70R19.5/16
 - RR706 315/80R22.5/20
 - RR706 11R24.5/16
 - RR716 315/80R22.5/22
 - RR905 385/65R22.5/20
 - RR202 315/80R22.5/20

If questions arise, please contact:
Double Coin engineering staff
at info@cmaintl.com

Yellow dot: Balance Mark - Valve System



White dot: Run Out (TMC Specs)